Approved For Release 2001/04/02 : CIA-RDP69B00041R001100010011-4 25X1A 25X1A

25X1A

25X1A 25X1A 25X1A 25X1A

сову якво

25X1A

	BLACK SHIELD CHECK LIST (as of 18 Aug 67) Msn Nr <u>BX 6732</u> H-hour <u>28 / 0230 g</u> 1130 L								
	H-Minus	ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials	
	-10:00	Send (Terminal, wx fcsts)	B - 5	В	27/1630	28/0130	0050	De la composição de la	
X1A	-9:00	Rev (GO-NO GO wx fests)	B-J.1	В	1730	0230	0200	An	
-	-9:00	Give input to Msn Coord	B-23	В	1730	0230	n200	Din	
X1A		Plot 12Z RODN & RAOBs	٦	Y	1700	0200	6200	MY	
	-8:00	Send (thru L-hr, if reqd)	B -1 6	В,А	1830	0330	;		
		Plot 12Z 30Mb Chart		Y	1800	0300	0320	5E	
		Brief tankers & annotate 175's	B-24	С				-	
	-4:00	Send (Terminal wx fcsts)	B - 5	С	2230	0730	0630	DM	
	-4:00	Send (Met Watch obs)	B-18	Z	2230	0730	07	SE	
	-3:50	Update		Z,X	2240	0740	0740	RAH	
The second secon		Brief tankers & annotate 175's	B-24	С					
	-3: 30	Brief pilots and ops staff	B-20	<u>A</u>	2300	0800	0800	Dels	
	25X1A	Brief tankers & annotate 175's	B-24	С					
The second secon	-3:00	Rcv Amend (GO/NO GO fcsts)	B -11	A	2330	0830	0734	Dels	
	-3:00	Rcv Letdown Plates from DCO	B-14	A	2330	0830	0830	Diff	
	-1:50 -3:00	Enter fcsts on Letdown Plates	B -1 4	A,C	28/0040	0940	0900	DAS	
	-2:30	Msn Obsvr to CP; posts data	B-13	Х	0000	0900	0900	RAH	
X1A	-2:00	Rcv (Wx Scout reports) #769/ (if needel	B-22	A 208 5	0030	0930	0830	DEB	
		Get ESSA-2 Pictures ASAP # 7692	-	z,c	0100	1000	0950	SE	
	-1:40	Msn Fcstr to CP; Obsvr to wx stn Letdown Plate fcsts to pilots	B-13	A,X	0050	0950	1030	DES	
2	-1:35	(Notify Mission Coordinator) Notify DCOL	B-14	A	0055	0955			
	-1:30	(If need to rebrief pilots)	B-20	A	0100	1000			
X1A	-1:10	Rebrief pilots if necessary *#7067 (4) needed Get Pictures ASAP # 7068			0120.	1020 1300 1500	11/22		
de la									
	L-Flus	Landing time Z L							
	+0:15	Return Met Watch to wx station	B-13	Х			1550	77	
	+0:15	Start debriefing form	B-15	A			1519	J/	
	+0:45	Attend pilot debriefing	B-15	A			1605	54	
5X1A		Give input to DCOM Coord after debriefing	B - 15	A	ASAP	ASAP	1610	77	
		Turn in Msn Wx File to Intell	B-17	A					

Approved For Release 2001/04/02 : CIA-RDP69B00041R001100010011-4

25X1A 25X1A 25X1A

and and an analysis		BLACK SHIELI				-		Page 1 of 2
ission	Nr BX6732	(As of 18 Aug 6				H-	•	0 Z 1130 L
ode Nan	ne BLACK SHIELD	Da ⁻	te_ <u></u>	00	ст 67	L L	-hour <u>, 063</u>	8 z <i>153</i> 81
ey Pers	sonnel	Duty Hours 2						
sn Pilo	ot			29/0800-1500L; 28/0600-1800L				
Spare Pi	ilot	B Fcstr			27/15	00-28	10100L	
hase Pi	ilot —			28/0100-1000L; THEN REST LOUNGEST				
Commande	er			27/1000-1800L; 28/0700-1700L				
Isn Coo	rd		27/1800-28/0300L					
4sn DCO	M	Z Obsvr	28/03-1100L 25					25X1/
Asn TTF	C -	EMBCY ROVRY	Fcs	<i>TJR</i> RESP	TIME	TIME	TIME	DONE BY
H-Minus					DUE(Z)	DUE(L)	DONE(L)	(Initials)
-24:00	Start this check list		B - 3	A	27/0230	1/1130	1130	DEB
-24:00	Arrange work schedule		B-4	A	0230	1130	0930	Dels
-23 :3 0	Attend Commander's Br	iefing	B -1	A	0300	1200	1200	WELS
-23:00	Rcv (Prelim Ops	Data)	B -1	Α	0330	1230	063.	77
	RCV WX SCOUT CALL SIGNS						1700	92581
	Give Msn Planning Fcs	t to TTFC		'C				25X1/
	Give Cre	ws Prelim Brfg	B 2	С	0300	1200		25X1A
	Give Crews I	relim Brfg	B - 2	С	0400	1300		25X1A
	Coordinate-Further T	FC Support	B - 2	С	0430	1330	-	·
-21:00	Rev (Tmnl fcst	us)	B-5	A	0530	1430	1346	Dest \$1/
-20:00	Start Met Watch on wa	all map	B-21	Α -	0630	1530	1630	TY
-21:00	Rev (Mission w	(data)	B 6	A	0530	1430	1357	DE5811
		,						
	Get ESSA-2 Pictures	#7679 #7680	B10	Х	0300	1200	1130	RAH
	Get Pictures	# 7054 # 7055	B - 10	Х	0530	1530	1530	RAH 25X1/
	Rev (Composit	e rte data)	B - 6	A	Vrbl	Vrbl	2032	5%
-17:30	Rcv Amend (Mis	sion wx)	B - 6	A	0900	1800	ja ja s	25X1/
-17:15	Rev (Tmnl fcs	ts)	B - 5	A	0915	1815	1750	27
-17:00	Brief pilot and ops		B - 7	A	0930	1830	1830	37/
-17:00	RCV LIST OF PRIMARY &	ż			0930	1830	0710	Jy
-14:00	¥ .	n wx fcst)	B - 9	В	1230	2/30	2100	T25X1/
-14100				Y	1200	2100	2100	53
		ase 2001/04/0:			1220	2220	12200	T25X1